RECEIVED
By Carol Day at 1:29 pm, Apr 14, 2014

MISSOURI DEPARTMENT OF HEA[illegible]
STATE PUBLIC HEALTH LABORATORY
BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPO[illegible]

Complete this report at the time of the regular monthly pr[illegible]
Complete this report whenever the instrument is serviced [illegible]
Retain the original and send a copy within 15 days to the [illegible]

DATAMASTER S/N	NAME OF AGENCY
204138	Missouri State Highway Patro[illegible]

LOCATION OF INSTRUMENT (STREET AND CITY)
Camden County Jail, Camdenton

CHECKLIST: Place a mark in the box by each item if found to [illegible] where determined.) Unmarked items must be corrected befo[illegible]

☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED) [illegible] 2051 [illegible]

☑ COMPUTER

☑ PROGRAM

☑ HEATERS SAMPLE CHAMBER 49 [illegible]

☑ FLOW DETECTOR

☑ PUMP HIGH SPEED

☑ INDICATOR LIGHTS

☑ SIMULATOR SOLUTION SUPPLIER Repco Market [illegible] DATE

☑ SIMULATOR TEMP (34°C ± 0.2°C) 33.99 [illegible] DATE

☑ CALIBRATION CHECK – (ONLY ONE STANDARD IS TO [illegible]

Run three tests using a standard solution. All three tests [illegible] have less. Mark the box corresponding to the standard solution [illegible]

☑ 0.100% STANDARD - MUST READ BETWEEN 0.09[illegible]
☐ 0.080% STANDARD - MUST READ BETWEEN 0.076[illegible]
☐ 0.040% STANDARD - MUST READ BETWEEN 0.038[illegible]

TEST 1 .100%	TEST 2 .101%

☑ PERFORM R.F.I. TEST (PRINTOUT ATTACHED)

INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING [illegible] (DO NOT INCLUDE SELF-ADMINISTERED TESTS)

REFUSALS	1	(0-.04)	20	(.05-.09)	1	[illegible]

LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS [illegible] (USE OTHER SIDE IF NECESSARY).

INSPECTING OFFICER

SIGNATURE

[illegible]

[illegible] EXPIRATION DATE
[illegible]1/14/2016

BAC Da[illegible]
Evidence Ticket

MISSOURI STATE [illegible]
BAC DATAMASTER [illegible]
[illegible]

--- DIAGNOS[illegible]

COMPUTER: [illegible]

PROGRAM [illegible]

HEATERS
SAMPLE CHAMBER: [illegible]

FLOW DETECTOR: [illegible]

PUMP
HIGH SPEED: [illegible]

DETECTOR: [illegible]

FILTERS: [illegible]

QUARTZ STANDARD: [illegible]

CALIBRATION: [illegible]

PRINTER [illegible]
[illegible]
[illegible]
[illegible]

Operator Signature [illegible] 1/96

BAC DataMast[illegible]
Evidence Ticke[illegible]

MISSOURI STATE HIGHWAY [illegible]
BAC DATAMASTER SERIAL NUMB[illegible]
04/03/14

TESTING OFFICER:
CUMMINGS/SCOTT/M
OFFICER I.D.: 196
PERMIT NUMBER: 240007
EXPIRATION DATE: 01/14/16
MISCELLANEOUS DATA:

--- SUPERVISOR MODE

BLANK TEST	.000
INTERNAL STANDARD	VER[illegible]
EXTERNAL STANDARD	.10[illegible]
BLANK TEST	.000
EXTERNAL STANDARD	.101
BLANK TEST	.000
EXTERNAL STANDARD	.101
BLANK TEST	.000

N = 3
STN. = .1
AVG. = .1006

[illegible]ator Signature [illegible]

BAC DataMaster
Evidence Ticket

[illegible] PATROL
[illegible] NUMBER 204138
[illegible]

[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]
[illegible]

OPERATOR ANALYSIS --

[illegible]	[illegible]	21:08
INTERNAL STANDARD	VERIFIED	21:08
[illegible]		

Operator Signature [illegible] #196