MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES
STATE PUBLIC HEALTH LABORATORY
BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT

received 5/12/14-cd

REPORT #6

Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days).
Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service.
Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.

REVIEWED
By Carol Day at 2:14 pm, May 19, 2014

DATAMASTER SN	NAME OF AGENCY	DATE OF INSPECTION
990044	Cape Girardeau P.D.	05/03/2014

LOCATION OF INSTRUMENT (STREET AND CITY)	TIME OF INSPECTION
40 S. Sprigg Cape Girardeau (BAT van)	3:58 pm

CHECKLIST: Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unmarked items must be corrected before using instrument.

☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED) DATE AND TIME (from printout) 05/03/2014 15:58

☑ COMPUTER ☑ DETECTOR

☑ PROGRAM ☑ FILTERS

☑ HEATERS SAMPLE CHAMBER 49 °C ☑ QUARTZ STANDARD

☑ FLOW DETECTOR ☑ CALIBRATION

☑ PUMP HIGH SPEED ☑ PRINTER

☑ INDICATOR LIGHTS

☑ SIMULATOR SOLUTION SUPPLIER RepCo Marketing Inc. LOT # 13802 EXP. DATE 08/12/2015

☑ SIMULATOR TEMP (34°C ± 0.2°C) 34.0 °C SIMULATOR SN SD2221 EXP. DATE 07/10/2014

☑ CALIBRATION CHECK – **(ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)**

Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)

☐ 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE
☑ 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE
☐ 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE

TEST 1 ☛ .081	TEST 2 ☛ .081	TEST 3 ☛ .081

☑ PERFORM R.F.I. TEST (PRINTOUT ATTACHED)

INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)

REFUSALS	(0-.04)	(.05-.09)	(.10-.14)	(.15-.19)	OVER .19
0	0	0	0	0	0

LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY).

INSPECTING OFFICER

SIGNATURE	PRINT FULL NAME
▸ #106	Kevin Eudy DSN 106

TYPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER
220132 06/12/2014	(573) 335-6621

RETURN COMPLETED REPORT TO THE: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office
2875 James Blvd.
Poplar Bluff, MO 63901

AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER
services provided on a nondiscriminatory basis

RepCo Marketing Inc

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc
LOT NUMBER: 13001
EXPIRATION DATE: March 7, 2015 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 13001 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain .1215 gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of .100 +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is March 8, 2013
The expiration date for this lot number is March 7, 2015 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner

Cecil B. Garner, President
RepCo Marketing, Inc.

Form RM 02

State of Missouri

DEPARTMENT OF HEALTH

PERMIT

TYPE II

KEVIN L EUDY

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

Date: 06/12/2012

Number: 220132

Expires: 06/12/2014

Director of State Public Health Laboratory

Director, Department of Health

MO 580-0771 (F-99)

Lab. 6 (57-98)

Face This Side Down – This Edge In First

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
SEMO LAW ENFORCEMENT ACADEMY

BAC DATAMASTER SERIAL NUMBER 990844
05/03/14

ARREST TIME: 15:30
SUBJECT NAME:
RFT/TEST
DOB: 12/22/45 SEX: F
STATE/D.L.: MO/098475
ARRESTING OFFICER:
NAN
OFFICER I.D.: 1
TESTING OFFICER:
EUDY/KEVIN/L
OFFICER I.D.: 186
PERMIT NUMBER: 228102
EXPIRATION DATE: 06/18/14
MISCELLANEOUS DATA:

--- BREATH ANALYSIS ---

BLANK TEST	.000	16:06
INTERNAL STANDARD	VERIFIED	16:06
RADIO INTERFERENCE		

rator Signature [signature]

2208-02

Face This Side Down – This Edge In First

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
SEMO LAW ENFORCEMENT ACADEMY

BAC DATAMASTER SERIAL NUMBER 990844
05/03/14

TESTING OFFICER:
EUDY/KEVIN/L
OFFICER I.D.: 186
PERMIT NUMBER: 228102
EXPIRATION DATE: 06/18/14
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLANK TEST	.000	16:01
INTERNAL STANDARD	VERIFIED	16:01
EXTERNAL STANDARD	.082	16:01
BLANK TEST	.000	16:05
EXTERNAL STANDARD	.082	16:07
BLANK TEST	.000	16:09
EXTERNAL STANDARD	.081	16:09
BLANK TEST	.000	16:04

N = 3
SUM. = .000
AVG. = .0000

Operator Signature [signature]

2208-02

Face This Side Down – This Edge In First

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
SEMO LAW ENFORCEMENT AGENCY

BAC DATAMASTER SERIAL NUMBER: 990944
05-03-14
15:58

--- DIAGNOSTIC CHECK ---

COMPUTER:	OKAY
PROGRAM (04-07,20090):	OKAY
HEATERS:	
SAMPLE CHAMBER:	OKAY
FLOW DETECTOR:	OKAY
PUMP	
HIGH SPEED:	OKAY
DETECTOR:	OKAY
FILTERS:	OKAY
QUARTZ STANDARD:	OKAY
CALIBRATION:	OKAY

PRINTER TEST

Operator Signature _____

2208-02