RECEIVED
By Carol Day at 8:22 am, Jul 28, 2016

# Day, Carol

**From:** Samel, Julianne <Julianne.Samel@mshp.dps.mo.gov>
**Sent:** Thursday, June 30, 2016 1:51 PM
**To:** Day, Carol
**Cc:** Conrad, Jonathan; Grubaugh, Philip
**Subject:** FW: MSHP-TROOP B OUT-OF-SERVICE ALCO-SENSOR IV'S

**Follow Up Flag:** Follow up
**Due By:** Wednesday, July 06, 2016 2:30 PM
**Flag Status:** Flagged

---

**From:** Conrad, Jonathan
**Sent:** Thursday, June 30, 2016 1:40 PM
**To:** Samel, Julianne <Julianne.Samel@mshp.dps.mo.gov>
**Cc:** Grubaugh, Philip <Philip.Grubaugh@mshp.dps.mo.gov>; Koch, William R. <William.Koch@mshp.dps.mo.gov>
**Subject:** AS-IV

**The AS-IVs assigned to Tpr. Phillip Grubaugh (Serial number: 107982) and myself (Serial number: 107984) are out of service. Both instruments need the capacitors replaced. I will take both of them down on July 6th and will get them fixed that day.**

Tpr. Jonathan M. Conrad #237
Missouri State Highway Patrol
Troop B - Zone 13
308 Pine Crest Drive
Macon, Missouri 63552
(660) 385-2132
Fax: (660) 385-3920