

## Day, Carol

---

**From:** Samel, Julianne  
<Julianne.Samel@mshp.dps.mo.gov>  
**Sent:** Thursday, June 30, 2016 1:51 PM  
**To:** Day, Carol  
**Cc:** Conrad, Jonathan; Grubaugh, Philip  
**Subject:** FW: MSHP-TROOP B OUT-OF-SERVICE  
ALCO-SENSOR IV'S

**Follow Up Flag:** Follow up  
**Due By:** Wednesday, July 06, 2016 2:30 PM  
**Flag Status:** Flagged

---

**From:** Conrad, Jonathan  
**Sent:** Thursday, June 30, 2016 1:40 PM  
**To:** Samel, Julianne <Julianne.Samel@mshp.dps.mo.gov>  
**Cc:** Grubaugh, Philip <Philip.Grubaugh@mshp.dps.mo.gov>; Koch, William R. <William.Koch@mshp.dps.mo.gov>  
**Subject:** AS-IV

The AS-IVs assigned to Tpr. Phillip Grubaugh (Serial number: 107982) and myself (Serial number: 107984) are out of service. Both instruments need the capacitors replaced. I will take both of them down on July 6<sup>th</sup> and will get them fixed that day.

Tpr. Jonathan M. Conrad #237  
Missouri State Highway Patrol  
Troop B - Zone 13  
308 Pine Crest Drive  
Macon, Missouri 63552  
(660) 385-2132  
Fax: (660) 385-3920