



Randall W. Williams, MD, FACOG Director

Michael L. Parson Governor

From: Missouri Radiation Control Program (MRCP) <u>MRCP@health.mo.gov</u> Phone 573-751-6083

To: Facilities having new x-ray rooms (or +1 machines) installed in Missouri

See below for your legal responsibilities in regard to your new x-ray machine/facility:

The installer/service company's only responsibilities to MRCP:

- To make sure x-ray equipment is installed according to manufacturer specifications and meets the federal performance standard for the appropriate piece of equipment.
- To send in notification of the installation to MRCP within 15 days of the install. (This is only the vendor paperwork, not the owner's.) In most cases for clinical x-ray equipment this is done via the FDA Form 2579.

<u>Note: The installer/service rep sending in certain paperwork to MRCP does NOT substitute or relieve the</u> facility from their responsibility to provide additional information and forms to MRCP.

Your responsibilities as a facility owning or controlling x-ray machines (required to legally utilize x-ray):

• If this is a new facility:

- Make sure your facility is registered with MRCP. (There is a 4 digit tracking number that will be assigned to your facility by MRCP. **If you do not know this number, assume you are NOT registered**.)
- Make sure all your x-ray machines are properly and accurately listed on your registration. (Your inventory of x-ray machines is updated and on file with MRCP).
- Contract/arrange with a MRCP-approved Qualified Expert (QE) to do a shielding evaluation and a radiation safety inspection on all machines. A list of Approved QE's is available on the MRCP website.
 QE's do this for a fee and it is your responsibility as equipment owner to make sure this is complete. This shielding evaluation and inspection by a QE must be done as follows:
 - Prior to routine clinical use if the machine is fluoro, C-arm, CT, mammo, or therapy;
 - Within 30 days of installation if the machine is Cone Beam CT (CBCT); and
 - Within 90 days of installation for all other equipment.
- Make sure a copy of shielding evaluation and QE summary report is sent to MRCP.
- If the QE finds a problem, it must be addressed within 30 days unless an emergency exists.

• If this is an already existing facility (you *already* have and know your MRCP Registration Number)

- Make sure your facility registration is updated with the new information.
- Is this an **additional**, **add-on** (+1) **machine**/x-ray room?
 - It needs a shielding evaluation and survey by a QE following the above time frames.
- Is this a **replacement of an existing machine** for a "like-kind" machine?
 - You *may* wish to contact a QE for consultation, but it is *not mandatory*.
 - Note: CBCT is an upgrade from pano, and requires an inspection within 30 days.
 - If you get rid of a machine, you must let MRCP know what happened to the machine, or the new owner. You can notify the MRCP via email. Please include your Registration # in the email.

• Going forward (Your Future Responsibilities)

- Update your facility's registration every two (2) years or when changes are made (facility moves, changes name or ownership, adds additional (+1) machines, cease using your machines, etc.)
- Get a new QE inspection based on your facility classification, or if you add a new (+1) room or move to a different location. (Ask MRCP if you are unsure of your classification or QE due date.)

<u>If you have any questions</u> about these requirements, or to ensure you are in compliance, contact MRCP via email <u>MRCP@health.mo.gov</u> or by phone at 573-751-6083 or check our website: <u>www.health.mo.gov/safety/radprotection/</u>

www.health.mo.gov Healthy Missourians for life.

The Missouri Department of Health and Senior Services will be the leader in promoting, protecting and partnering for health. AN EQUAL OPPORTUNITY / AFFIRMATIVE ACTION EMPLOYER: Services provided on a nondiscriminatory basis.

(rev. 2/18)