



MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES  
 STATE PUBLIC HEALTH LABORATORY  
**ALCO-SENSOR IV WITH PRINTER MAINTENANCE REPORT**

RECEIVED  
 07/19/09 Closed at 11:48am, Nov 04

REPORT #7

Complete this report in duplicate at the time of the regular monthly preventative maintenance check, and whenever instrument is repaired. Send copy to Department of Health and Senior Services; retain original in department file.

ALCO SENSOR IV SN 111629	NAME OF AGENCY University of Missouri Police Department	DATE OF INSPECTION 11/05/2024
LOCATION OF INSTRUMENT (STREET AND CITY) 901 Virginia Ave, Columbia, Missouri		TIME OF INSPECTION 11:54 am

**CHECKLIST:** Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unmarked items must be corrected before using instrument.

- DIGITAL READOUT (ALL ELEMENTS OPERATIONAL)
- TEMPERATURE OF ALCO SENSOR (10°C - 40°C)
- PRINTER WORKING PROPERLY
- TIME AND DATE DISPLAYING PROPERLY

**BREATH ALCOHOL ACCURACY STANDARDS**

<input type="checkbox"/> SIMULATOR SOLUTION	<input type="checkbox"/> COMPRESSED ETHANOL-GAS MIXTURE
<input checked="" type="checkbox"/> STANDARD SUPPLIER <u>Intoximeters</u>	LOT # <u>AG331701</u> EXP. DATE <u>11/13/2025</u>
<input type="checkbox"/> SIMULATOR TEMPERATURE (34°C ± 0.2°C) _____	SIM. SN _____ SIM. NIST EXP DATE _____

CALIBRATION CHECK – (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)  
 Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)

- 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE
- 0.080% STANDARD - MUST READ BETWEEN 0.076% and 0.084% INCLUSIVE
- 0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE

TEST 1  .080	TEST 2  .079	TEST 3  .079
--------------	--------------	--------------

RFI DETECTOR OPERATING

INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:  
 (DO NOT INCLUDE SELF-ADMINISTERED TESTS)

REFUSALS	(0-.04)	(.05-.09)	(.10-.14)	(.15-.19)	(OVER .19)
----------	---------	-----------	-----------	-----------	------------

List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary).  
 Time updated.

**INSPECTING OFFICER**

SIGNATURE 	PRINT NAME Kyle Townley
TYPE II PERMIT NUMBER/EXPIRATION DATE 230234 11-24-2025	TELEPHONE NUMBER (573) 882-7201

Return completed report to the: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office by mail, fax, or email.

AS IV Serial no: 111629  
Version no: 532B

TEST RECORD 01808

Temp Date Time 21<sup>9/</sup>OL

Air Blank:  
11/05/24 11:54 .000  
Calibration Check:  
22 11/05/24 11:54 .080

Subject Name

Townley - Test 1

Subject I.D.

Townley 230234

Operator Name, I.D.

Maintenance

Location

901 Virginia Ave

Columbia MO 65211

AS IV Serial no: 111629  
Version no: 532B

TEST RECORD 01810

Temp Date Time 21<sup>9/</sup>OL

Air Blank:  
11/05/24 11:57 .000  
Calibration Check:  
23 11/05/24 11:57 .079

Subject Name

Test 3

Subject I.D.

Maintenance

Operator Name, I.D.

Townley 230234

Location

901 Virginia Ave

Columbia MO 65211

AS IV Serial no: 111629  
Version no: 532B

TEST RECORD 01809

Temp Date Time 21<sup>9/</sup>OL

Air Blank:  
11/05/24 11:55 .000  
Calibration Check:  
23 11/05/24 11:55 .079

Subject Name

Test 2

Subject I.D.

Maintenance

Operator Name, I.D.

Townley 230234

Location

901 Virginia Ave

Columbia MO 65211

AS IV Serial no: 111629  
Version no: 532B

TEST RECORD 01811

Temp Date Time 21<sup>9/</sup>OL

VOID: RF1  
12 11/05/24 11:58

Subject Name

RFI Test

Subject I.D.

Maintenance

Operator Name, I.D.

Townley 230234

Location

901 Virginia Ave

Columbia MO 65211