

## MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

## INTOX DMT MAINTENANCE REPORT

REPORT #1

WARREST TINTON DIVIT WINDING TENNINGE IN				
Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.				
NAME OF AGENCY S00271 Perryville PD		DATE OF INSPE 11/01/20		
LOCATION OF INSTRUMENT (STREET AND CITY) 120 N. Jackson St., Perryville		TIME OF INSPEC 05:04:31		
CHECKLIST: Place a mark in the box by each item if found to be satisfactory or is operating within established limits. (Write in observed values where determined). Unmarked items must be corrected before using instrument.				
☑ DIAGNOSTIC RECORD				
DATE AND TIME11/01/2024 05:04:34				
☑ PROGRAM ☑ FILTER 1				
SAMPLE CHAMBER 48.8°C				
☐ BREATH TUBE 47.7°C ☐ ☐ FILTER 3				
☑ PUMP ☑ INTERNAL STANDARD				
BREATH ANALYZER ACCURACY STANDARDS				
☐ SIMULATOR STANDARD ☐ COMPRESSED ETHANOL-GAS MIXTURE				
☐ STANDARD SUPPLIER INTOXIMETERS	LOT# AG40	<u>0203</u> ЕХР. С	DATE 01/02/2026	
☐ SIMULATOR TEMP (34°C ± 0.2°C)	SIM. SN	SIM. NIST EX	P DATE	
<ul> <li>□ CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) Run three tests using a standard. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard being used.</li> <li>□ 0.10% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE</li> <li>□ 0.08% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE</li> <li>□ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE</li> </ul>				
TEST 1: 0.099 TES1	72: 0.098	TEST 3: 0.	TEST 3: 0.099	
☑ PERFORM R.F.I. TEST				
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:				
REFUSALS: 1 004: 1 .050	09: 0 .10	l4: 0 .1519: <b>0</b>	OVER .19: 0	
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY)	IN THAT WAS MADE TO RESTOR	THE INSTRUMENT TO OPERATE SATISFA	ACTORILY AND WITHIN	
INSPECTING OFFICER	LODINT	FULL NAME		
SIGNATURE (S) Justa MMM		STIN M MILLER		
TYPE II PERMIT NUMBER 240066	03/07/2026	TELEPHONE NUMBER 573-547-4546		
RETURN COMPLETED REPORT TO THE Breath Alcohol Program, Missouri Department of Health and Senior Services by mail, fax, or email				