

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

INTOX EC/IR II	MAINTENANCE	REPORT		REPORT #3
Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35				
days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.				
into service. Retain the original a	name of agency		DATE OF INSPECTION	ogram, bibb.
12828	WARRENSBURG POLI	CE DEPT	01/16/2025	
LOCATION OF INSTRUMENT (STREET AND CITY)			TIME OF INSPECTION	
102 S HOLDEN ST SUITE B WARRENSBURG		03:56 CST		
CHECKLIST: Place a mark in the box by each item if found to be satisfactory or is operating within				
established limits. (Write in observed values where determined). Unmarked items must be corrected				
before using instrument.				
X DIAGNOSTIC RECORD				
X BLANK CHECK X CO2 CHECK				
X FC 1 TEMP X FLOW CHECK				
X SRC TEMP X FCB CHECK				
X DET TEMP X CRC COMP CHECK				
X BT TEMP X CRC CAL CHECK				
X STD 2 TEMP X PRINT TEST				
X ETH CHECK				
BREATH ANALYZER ACCURACY STANDARDS				
SIMULATOR SOLUTION X COMPRESSED ETHANOL-GAS MIXTURE				
X STANDARD SUPPLIER INTOXIMETERS LOT# AG323603		EXP. DATE 08/24/2025		
SIMULATOR TEMP (34°C ±0.2°C)	SIM. S	SN	SIM. NIST EXP	DATE
_				
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)				
Run three tests using a standard solution. All three tests must be within +5% of the standard value				
and must have a spread of .005 or less. Mark the box corresponding to the standard solution being				
used.				
0.10% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE				
X 0.08% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE				
0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE				
TEST 1 0.078 g/210L	TEST 2 0.078 g/210L		TEST 3 🙉 0.078 g/210L	
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:				
REFUSALS 0 004 0	.0509 1	.10~.14 0	.1519 1	OVER .19 1
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY).				
DATIONACIONED WITHIN BOTTLESS DE LEGIS CON CONTRACTOR DE LA CONTRACTOR DE				
INCOROTING OPETOED	THE RESERVE TO SE	121123113		INVESTIGATION EST
INSPECTING OFFICER	SAN THE PARTY OF	PRINT FULL NAME		m 医压力 (2) 有状的 医格勒氏
E C )/////	132 PRINDLE, JACO		PΒ	
	TION DATE	TELEPHONE NUMBER		
230128 06/2	0/2025	(660)747-9133		
RETURN COMPLETED REPORT TO THE:				
Breath Alcohol Program, Missouri Department of Health and Senior Services,				
by mail, fax, or e-mail				