



MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES  
 STATE PUBLIC HEALTH LABORATORY  
 BREATH ALCOHOL PROGRAM  
**DATAMASTER MAINTENANCE REPORT**

received 1/18/14 REPORT # 6

Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days).  
 Complete this report whenever the Instrument is serviced or repaired and whenever it is placed into service.  
 Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.

**REVIEWED**  
 By Carol Day at 2:13 pm, Feb 06, 2014

DATAMASTER SN 204148	NAME OF AGENCY Missouri State Highway Patrol	DATE OF INSPECTION 01/11/2013
LOCATION OF INSTRUMENT (STREET AND CITY) 110 W. Elm St. Room 70 Ozark		TIME OF INSPECTION 2020

**CHECKLIST:** Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unmarked items must be corrected before using instrument.

<input checked="" type="checkbox"/> DIAGNOSTIC CHECK (PRINTOUT ATTACHED)	DATE AND TIME (from printout) 01/11/14 20:20
<input checked="" type="checkbox"/> COMPUTER	<input checked="" type="checkbox"/> DETECTOR
<input checked="" type="checkbox"/> PROGRAM	<input checked="" type="checkbox"/> FILTERS
<input checked="" type="checkbox"/> HEATERS SAMPLE CHAMBER 49 °C	<input checked="" type="checkbox"/> QUARTZ STANDARD
<input checked="" type="checkbox"/> FLOW DETECTOR	<input checked="" type="checkbox"/> CALIBRATION
<input checked="" type="checkbox"/> PUMP HIGH SPEED	<input checked="" type="checkbox"/> PRINTER

INDICATOR LIGHTS

SIMULATOR SOLUTION SUPPLIER RepCo Marketing Inc. LOT # 13001 EXP. DATE 03/07/2015

SIMULATOR TEMP (34°C ± 0.2°C) 34.2 °C SIMULATOR SN G11046 EXP. DATE 03/26/2014

CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)

Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)

0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE  
 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE  
 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE

TEST 1 0.095%	TEST 2 0.097%	TEST 3 0.097%
---------------	---------------	---------------

PERFORM R.F.I. TEST (PRINTOUT ATTACHED)

INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:  
 (DO NOT INCLUDE SELF-ADMINISTERED TESTS)

REFUSALS 0	(0-.04) 5	(.05-.09) 2	(.10-.14) 3	(.15-.19) 2	OVER .19 0
------------	-----------	-------------	-------------	-------------	------------

LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY).

Alcohol Vapor Concentration .100% Bottle #166 Lot #13001 RepCo Marketing Inc.

**INSPECTING OFFICER**

SIGNATURE Michael W. Lee	PRINT FULL NAME Michael W. Lee
TYPE II PERMIT NUMBER/EXPIRATION DATE 220217 09/04/2014	TELEPHONE NUMBER (417) 895-6868

RETURN COMPLETED REPORT TO THE:  
 Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office  
 2875 James Blvd.  
 Poplar Bluff, MO 63901

**CERTIFICATE OF ANALYSIS**

**MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc.**

**LOT NUMBER: 13001**

**EXPIRATION DATE: March 7, 2015 at 11:59 p.m.**

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 13001 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain .1215 gms/dl +/-0.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of .100 +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is March 8, 2013  
The expiration date for this lot number is March 7, 2015 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.



Cecil B. Garner, President  
RepCo Marketing, Inc.

**BAC DataMaster**  
Evidence Ticket

MISSOURI STATE HIGHWAY PATROL  
BAC DATAMASTER SERIAL NUMBER 204148  
01/11/14

TESTING OFFICER:  
LEE/M/W  
OFFICER I.D.: 842  
PERMIT NUMBER: 220217  
EXPIRATION DATE: 09/04/14  
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---  
BLANK TEST .000 20:31  
INTERNAL STANDARD .095 20:32  
EXTERNAL STANDARD .000 20:33  
BLANK TEST .097 20:33  
EXTERNAL STANDARD .000 20:34  
INTERNAL STANDARD .097 20:35  
BLANK TEST .000 20:35

y = 3  
SIM. = .1  
RWS. = .0963

Signature M.W. LEE

**BAC DataMaster**  
Evidence Ticket

MISSOURI STATE HIGHWAY PATROL  
BAC DATAMASTER SERIAL NUMBER 204148  
01/11/14

ARREST TIME: 19:30  
SUBJECT NAME:  
TEST/RR/I  
DOB: 01/01/90 SEX: M  
STATE/D.L.: MO/123456  
ARRESTING OFFICER:  
LEE/M/W  
OFFICER I.D.: 842  
TESTING OFFICER:  
LEE/M/W

OFFICER I.D.: 842  
PERMIT NUMBER: 220217  
EXPIRATION DATE: 09/04/14  
MISCELLANEOUS DATA:  
--- BREATH ANALYSIS ---  
BLANK TEST .000 20:38  
INTERNAL STANDARD .095 20:38  
RADIO INTERFERENCE .000 20:38

Signature M.W. LEE

**BAC DataMaster**  
Evidence Ticket

MISSOURI STATE HIGHWAY PATROL  
BAC DATAMASTER SERIAL NUMBER 2041  
01/11/14  
20:29

--- DIAGNOSTIC CHECK ---

COMPUTER: OKAY  
PROGRAM (04-97-2009): OKAY  
HEATERS  
SAMPLE CHAMBER: 49c  
FLOW DETECTOR: OKAY  
PUMP  
HIGH SPEED: OKAY  
DETECTOR: OKAY  
FILTERS: OKAY  
QUARTZ STANDARD: OKAY  
CALIBRATION: OKAY  
PRINTER TEST  
!@#%&'()\*+,-./0123456789:;<=>?@A  
HIJKLMNOPQRSTUVWXYZ[\]^\_`abcedefgh  
ijklmnopqrstuvwxyz{|}~

Signature M.W. LEE

State of Missouri  
DEPARTMENT OF HEALTH



P E R M I T  
TYPE II



MICHAEL W LEE

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

Date 09/04/2012

Number 220217

Expires 09/04/2014

Director of State Public Health Laboratory

Director, Department of Health