

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

INTOX EC/IR II MAINTENANCE REPORT

REPORT #3

Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed									
into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.									
INTOX EC/IR II SN	and send a copy within 15 days to the		DATE OF INSPECTION						
12829	RAYTOWN POLICE DEPT		05/03/2022						
LOCATION OF INSTRUMENT (STREET AND CITY			TIME OF INSPECTION						
10000 E 59TH STREET RAYTOWN			14:24 CDT						
CHECKLIST: Place a mark in the box	he cash item if found	to be estiminate	· -	a within					
established limits. (Write in obse									
before using instrument.	ived values where decei	imineu). Oimaik	ed Items must be t	corrected					
X DIAGNOSTIC RECORD									
X BLANK CHECK	_	CO2 CHECK							
									
X FC 1 TEMP		FLOW CHECK							
X SRC TEMP	2	FCB CHECK							
X DET TEMP	Х	CRC COMP CHEC	ĽK						
X BT TEMP	2	CRC CAL CHECK	ζ						
X STD 2 TEMP		X PRINT TEST							
X ETH CHECK		X IIIIII IIDI							
BREATH ANALYZER ACCURACY STANDA									
SIMULATOR SOLUTION	X	COMPRESSED ET	HANOL-GAS MIXTU	RE					
X STANDARD SUPPLIER Intox	imeters LO	T# AG107601	EXP. DATE 03/17/2023						
SIMULATOR TEMP (34°C +0.2°C)	SIM. SN		SIM. NIST EXP I	DATE					
-									
CAT THE AMERICAN CHIEGO CANTAL CANTAL									
X CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)									
	S SIANDARD IS IC BE	USED PER MAINT	ENANCE REPORT)						
Run three tests using a stand	dard solution. All	three tests mu	st be within <u>+</u> 5%						
Run three tests using a stand and must have a spread of .00	dard solution. All	three tests mu	st be within <u>+</u> 5%						
Run three tests using a stand and must have a spread of .00 used.	dard solution. All	three tests mu e box correspo	st be within <u>+</u> 5% nding to the sta						
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ	dard solution. All of or less. Mark the BETWEEN 0.095% AND	three tests mu e box correspo	st be within ±5% nding to the sta						
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND	three tests mu e box correspo 0.105% INCLUSI 0.084% INCLUSI	st be within <u>+</u> 5% nding to the sta .VE .VE						
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND	three tests mu e box correspo 0.105% INCLUSI 0.084% INCLUSI	st be within <u>+</u> 5% nding to the sta .VE .VE						
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ	dard solution. Allo 05 or less. Mark th BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND	three tests mu e box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI	st be within <u>+</u> 5% anding to the standard to t	andard solution being					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND	three tests mu e box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI	st be within <u>+</u> 5% nding to the sta .VE .VE	andard solution being					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND	three tests mu the box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI	st be within ±5% nding to the state very very very very very very very ver	andard solution being					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND	three tests mu the box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI	st be within ±5% nding to the state very very very very very very very ver	andard solution being					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/	three tests mu the box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI	st be within ±5% nding to the state very very very very very very very ver	andard solution being					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT.	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING CO.0509 0	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L RG RANGES SINC	st be within +5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TO COME 1.00	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING CO.0509 0	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L RG RANGES SINC	st be within +5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED L.	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/FESTS IN THE FOLLOWING CONTROL OF MODIFICATION OF MODIFICATION OF MODIFICATION THE IMITS (USE OTHER SIDE IF MODIFICATION OF MO	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L ING RANGES SINCE 1014 0 HAT WAS MADE TO RESERVED.	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT.	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/FESTS IN THE FOLLOWING CONTROL OF MODIFICATION OF MODIFICATION OF MODIFICATION THE IMITS (USE OTHER SIDE IF MODIFICATION OF MO	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L ING RANGES SINCE 1014 0 HAT WAS MADE TO RESERVED.	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED L.	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/FESTS IN THE FOLLOWING CONTROL OF MODIFICATION OF MODIFICATION OF MODIFICATION THE IMITS (USE OTHER SIDE IF MODIFICATION OF MO	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L ING RANGES SINCE 1014 0 HAT WAS MADE TO RESERVED.	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TO COMMENT AND NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED L. MONTHLY MAINTENANCE OERFORMED	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/FESTS IN THE FOLLOWING CONTROL OF MODIFICATION OF MODIFICATION OF MODIFICATION THE IMITS (USE OTHER SIDE IF MODIFICATION OF MO	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L ING RANGES SINCE 1014 0 HAT WAS MADE TO RESERVED.	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED L. MONTHLY MAINTENANCE OERFORMED LINES	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/FESTS IN THE FOLLOWING CONTROL OF MODIFICATION OF MODIFICATION OF MODIFICATION THE IMITS (USE OTHER SIDE IF MODIFICATION OF MO	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI 210L ING RANGES SINCE 1014 0 HAT WAS MADE TO RESERVED.	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LINES INSPECTING OFFICER	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/FESTS IN THE FOLLOWITH THE FOL	three tests mule box corresponded to the correspondence of the cor	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED L. MONTHLY MAINTENANCE OERFORMED LINES	dard solution. All of or less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING 1.0509 0 CERATION OR MODIFICATION TRIMITS (USE OTHER SIDE IF MAND FOUND TO BE WIT:	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI /210L ING RANGES SINC 1014 0 HAT WAS MADE TO RES NECESSARY). THIN MODHSS GUI	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LINES INSPECTING OFFICER SIGNATURE MONTHLY MAINTENANCE OERFORMED LINES	dard solution. All objoint less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING .0509 0 . ERATION OR MODIFICATION TRIMITS (USE OTHER SIDE IF N AND FOUND TO BE WITH	three tests mule box corresponded to the correspondence of the cor	st be within ±5% anding to the state to the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LINES INSPECTING OFFICER SIGNATURE TYPE IT PERMIT NUMBER EXPIRED	dard solution. All object of less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 ** 0.099 g/ FESTS IN THE FOLLOWING .0509 0 . BERATION OF MODIFICATION TRAINITS (USE OTHER SIDE IF N AND FOUND TO BE WITH	three tests mu te box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI (210L MG RANGES SINC 1014 0 HAT WAS MADE TO RES NECESSARY). CHIN MODHSS GUI PRINT FULL NAME PORCH ELEPHONE NUMBER	st be within ±5% anding to the state of the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LINES INSPECTING OFFICER SIGNATURE TYPE IT PERMIT NUMBER 0.05/1	dard solution. All object of less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING .0509 0 . FRATION OR MODIFICATION TRAINITS (USE OTHER SIDE IF N AND FOUND TO BE WITH ATION DATE	three tests mu e box correspo 0.105% INCLUSI 0.084% INCLUSI 0.042% INCLUSI (210L ING RANGES SINC 1014 0 HAT WAS MADE TO RES NECESSARY). THIN MODHSS GUI RINT FULL NAME PORCH	st be within ±5% anding to the state of the	endard solution being g/210L FENANCE REPORT: OVER .19 1					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.0099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LINES INSPECTING OFFICER SIGNATURE TYPE IT PERMIT NUMBER . EXPIRE 200174 05/1 RETURN COMPLETED REPORT T	dard solution. All object of less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING .0509 0 . FRATION OR MODIFICATION THE IMITS (USE OTHER SIDE IF N AND FOUND TO BE WIT: 5/2022 (three tests muse box correspondence of the b	st be within ±5% anding to the state of the	endard solution being 9 g/210L FENANCE REPORT: OVER .19 1 TO OPERATE					
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.099 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.099 g/210L REFUSALS 0 004 0 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LINES INSPECTING OFFICER SIGNATURE TYPE IT PERMIT NUMBER 0.05/1	dard solution. All object of less. Mark the BETWEEN 0.095% AND BETWEEN 0.076% AND BETWEEN 0.038% AND TEST 2 0.099 g/ FESTS IN THE FOLLOWING .0509 0 . FRATION OR MODIFICATION THE IMITS (USE OTHER SIDE IF N AND FOUND TO BE WIT: 5/2022 (three tests muse box correspondence of the b	st be within ±5% anding to the state of the	endard solution being 9 g/210L FENANCE REPORT: OVER .19 1 TO OPERATE					



Airgas USA LLC (LAB)

3500 Bernard Street

St. Louis, Mo. 63103

Ph: (314) 533-3100

Fax: (314) 533-7328

Certificate of Analysis

Customer Name

Exclusive Supplier Intoximeters, Inc. 2081 Craig Road St. Louis, Mo 63146 Test Date: 17-Mar-2021

Lot # AG107601 Model 108cacd

Exp. Date 17-Mar-2023 Cyl. Type

Component

Certified Concentration 0.100 ± 2% BrAC (272 ppm)

Ethanol

Balance

Nitrogen

Certification Traceable to N.I.S.T. RGM and to CRM Ethanol Standards:

RGM Serial No.	<u>Concentration</u>	RGM Serial No.	<u>Concentration</u>
EB0010581	392.1 ppm	EB0010603	393.0 ppm
EB0010570	259.8 ppm	EB0010559	258.2 ppm
EB0010285	208.0 ppm	EB0010595	208.3 ppm
EB0010561	103.6 ppm	EB0010562	104.2 ppm
EB0010681	52.12 ppm	EB0010579	52.81 ppm
CRM Serial No. CC727481	Concentration 800.0 ppm	CRM Serial No. CC727493	Concentration 390.0 ppm

CC727498

Analytical Method:

CC727496

NDIR

253.0 ppm

Approved for Release:

More the

150.0 ppm

ISO 17025:2005 A2LA accredited. Certificate Number 3082.06 ISO 17034:2016 A2LA accredited. Certificate Number 3082.07



STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM



PERMIT TYPE II

BRIAN K PORCH

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

INTOX EC/IR II

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

DATE	5/15/2020	Went
DAIL		DIRECTOR OF STATE PUBLIC HEALTH LABORATORY
NUMBER	200174	
	5/15/2022	for Ulle
		DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES

MO 580-0771 (6-10)

LAB-4 (R6-10)



STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES BREATH ALCOHOL PROGRAM

INSTRUMENT OPERATOR CARD

The named cardholder is authorized to operate an evidential breath alcohol instrument for the determination of the alcoholic content in breath form of expired at in Missouri.



Operator PORCH, BRIAN

Permit No 200174

Date Issued 5/15/2020 Date Expires 5/15/2022