

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY

ALCO-SENSOR IV WITH PRINTER MAINTENANCE REPORT

REPORT #7

-4EG(**					
Complete this report in duplicate at the time of Send copy to Department of Health and Senio				henever instrument is repaired.	
NAME OF AGENCY AURORA POLICE DEPARTMENT				TE OF INSPECTION 2/01/2024	
LOCATION OF INSTRUMENT (STREET AND CITY) 106 S. ELLIOTT, AURORA, MO. 65605				ME OF INSPECTION 56 pm	
CHECKLIST: Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values					
where determined.) Unmarked items must be corrected before using instrument.					
DIGITAL READOUT (ALL ELEMENTS OPERATIONAL)					
☑ TEMPERATURE OF ALCO SENSOR (10°C - 40°C)					
PRINTER WORKING PROPERLY					
☑ TIME AND DATE DISPLAYING PROPERLY					
BREATH ALCOHOL ACCURACY STANDARDS					
SIMULATOR SOLUTION COMPRESSED ETHANOL-GAS MIXTURE					
STANDARD SUPPLIER GUTH LABS LOT # 24110 EXP. DATE 03/05/2026					
☑ SIMULATOR TEMPERATURE (34°C ± 0.	.2°C) <u>34.02</u> SIN	и. SNSD225	8 SIM. NIS	ST EXP DATE <u>08/26/2025</u>	
less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) ☑ 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE ☐ 0.080% STANDARD - MUST READ BETWEEN 0.076% and 0.084% INCLUSIVE ☐ 0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE					
TEST 1100	.100 TEST 2100		TEST 3 ▼ .100		
☑ RFI DETECTOR OPERATING					
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)					
REFUSALS 1 (004) 0	(05.00) 0	(10.14) 0	(15-10)) (OVER 19) 0	
List any new parts and describe any alteration established limits (use other side if necessary	on or modification that v	L			
INSPECTING OFFICER	생물 (1885년 1885년 - 1885	New York Control			
SIGNATURE			PRINT NAME TATUM MAPLES		
17PE II PERMIT NUMBER/EXPÍRATION DATE 240192 08/29/2026			TELEPHONE NUMBER (417) 678-5025		
Return completed report to the: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office by mail, fax, or email.					

CELLBRANCE CHECKS . 876 . 12781/24 21:56 . 876 . 12781/24 21:56 . 128 Version not 11700 Tear Date Time 2101 Selp test #) Youra, Mo- Lesses Tatum Maples
== 240197
== 24019726 S. Elliat

> Hurara mo lestess 91r Wlenk: 12/81/24 22:82 .988 03110ration Check: 22 12/81/24 22:82 .188 106 S. ElijoH 10 tum McpLJ 8/29/26 Scholect Name #2 TEMP Date Time 2181 Persion not 500g

1074 M M. 5/5 #240182 Aurora, mo issues Hole s. Ellioft

SC | Trest # 3 Mersion mo: 532B

CANCELLO DELL'ANDIONE DELL'ANDI

Tens Date Time 2181

T T

Tatum Maples #2401922 106 S- EllioH

Hurora, MD. 105605



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 24110 of
Alcohol Reference Solution for Simulator were analyzed by
gas chromatography on March 6, 2024, using a Perkin Elmer Gas
Chromatograph Autosystem XL S/N: 610N9030209, and found to contain
0.1215% (w/vol) ethyl alcohol. The expiration date for this lot
number is March 5, 2026 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN03072301 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.