

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

INTOX EC/IR II MAINTENANCE REPORT

REPORT	±٦

				REPORT #3
Complete this report at the time o	f the regular monthl	y preventive main	enance check (not	to exceed 35
days). Complete this report whenev	er the instrument is	serviced or repa:	ired and whenever	it is placed
into service. Retain the original	and send a copy with	in 15 days to the		ogram, DHSS.
12827			DATE OF INSPECTION	
LOCATION OF INSTRUMENT (STREET AND CITY	Smithville Police	e vept.	06.19.2024	
107 W Main Street Smithville)		TIME OF INSPECTION	
· · · · · · · · · · · · · · · · · · ·			22:22 CDT	
CHECKLIST: Place a mark in the box	by each item if fou	nd to be satisfact	cory or is operation	ng within
established limits. (Write in obse before using instrument.	rved values where de	termined). Unmark	red items must be	corrected
X DIAGNOSTIC RECORD				
X BLANK CHECK		PHOOD CYTHOL		
X FC 1 TEMP		X CO2 CHECK		
l formal		X FLOW CHECK		
X SRC TEMP		X FCB CHECK		
X DET TEMP		X CRC COMP CHE	SK .	
X BT TEMP		X CRC CAL CHEC	ζ	
X STD 2 TEMP		X PRINT TEST		
X ETH CHECK				
BREATH ANALYZER ACCURACY STANDA	ARDS			
SIMULATOR SOLUTION		X COMPRESSED E	THANOL-GAS MIXTU	RR
X STANDARD SUPPLIER Intox	imeters	LOT# AG306807		DATE 03.09.2025
SIMULATOR TEMP (34°C +0.2°C)	SIM. S			
	orm. o	IN	SIM. NIST EXP	JATE
X CALIBRATION CHECK - (ONLY ON)	R STANDARD IS TO B			
	- D	E USED PER MAINT	ENANCE REPORT)	
Run three tests using a stand	dard solution. Al	l three tests mu	st be within +59	of the standard value
Run three tests using a stand and must have a spread of .00	dard solution. Al	l three tests mu	st be within +59	s of the standard value andard solution being
Run three tests using a stand and must have a spread of .00 used.	dard solution. Al D5 or less. Mark	l three tests mu the box correspo	est be within ±59 onding to the sta	s of the standard value andard solution being
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ	dard solution. Al 05 or less. Mark BETWEEN 0.095% AN	l three tests muthe box correspo	st be within ±5% anding to the sta	s of the standard value andard solution being
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN	l three tests muthe box correspo D 0.105% INCLUSI D 0.084% INCLUSI	st be within ±5% onding to the sta	s of the standard value andard solution being
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN	l three tests muthe box correspo D 0.105% INCLUSI D 0.084% INCLUSI	st be within ±5% onding to the sta	s of the standard value andard solution being
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ	dard solution. Al 05 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN	l three tests muthe box corresponding of the box corresponding of the box corresponding of the box	st be within ±5% onding to the sta	s of the standard value andard solution being
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN	l three tests muthe box corresponding of the box corresponding of the box corresponding of the box	st be within ±5% onding to the sta	andard solution being
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN	three tests muthe box correspond 0.105% INCLUSID 0.084% INCLUSID 0.042% INCLUSID 0.042% INCLUSID	st be within ±5% anding to the state. VE VE VE TEST 3 0.098	andard solution being B g/210L
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN	three tests muthe box correspond 0.105% INCLUSID 0.084% INCLUSID 0.042% INCLUSID 0.042% INCLUSID	st be within ±5% anding to the state. VE VE VE TEST 3 0.098	andard solution being B g/210L
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TEFUSALS 0 004 5	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN TEST 2 0.098 FESTS IN THE FOLLO	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TEFUSALS 0 004 5	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTO	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALTY SATISFACTORILY AND WITHIN ESTABLISHED LIST	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the box	sst be within ±59 anding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TEST 1 0.098 g/210L REFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LIST AND WITHIN ESTABLISH AND	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.036% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TEST 0.098 TEST N THE FOLLOWARD CONTRACTOR OF MODIFICATION OF MODIFICATION	three tests muthe box corresponding of the local state of the local st	st be within ±59 onding to the sta VE VE TEST 3 0.098 TE THE LAST MAINT .1519 1 STORE THE INSTRUMENT	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TO SATISFACTORILY AND WITHIN ESTABLISHED LEST SATISFACTORILY AND WITHIN ESTABLISHED LEST SIGNATURE SIGNATURE EXPIRE EXPIRE TYPE II PERMIT NUMBER EXPIRE EXPIRE EXPIRE TYPE II PERMIT NUMBER EXPIRE EXPIR	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TESTS IN THE FOLLOW OF MODIFICATION OF MODIFICATION IMITS (USE OTHER SIDE IMITS (USE OTHER SIDE IMITS)	three tests muthe box correspond of the local section of the local secti	st be within ±59 onding to the sta VE VE TEST 3 0.098 TE THE LAST MAINT .1519 1 STORE THE INSTRUMENT	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TO SATISFACTORILY AND WITHIN ESTABLISHED LEST SATISFACTORILY AND WITHIN ESTABLISHED LEST SIGNATURE SIGNATURE EXPIRE EXPIRE TYPE II PERMIT NUMBER EXPIRE EXPIRE EXPIRE TYPE II PERMIT NUMBER EXPIRE EXPIR	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TESTS IN THE FOLLOWING CONTROL OF MODIFICATION OR MODIFICATION CONTROL OF MODIFI	three tests muthe box correspond of the local correspo	st be within ±5% onding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TREFUSALS 0 004 5 LIST ANY NEW PARTS AND DESCRIBE ANY ALT SATISFACTORILY AND WITHIN ESTABLISHED LEST STANDARD STAN	dard solution. Al D5 or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TESTS IN THE FOLLO COSTON OF MODIFICATION IMITS (USE OTHER SIDE IMITS (USE OTHE	three tests muthe box correspond of the local correspo	st be within ±5% onding to the state to the	andard solution being B g/210L CENANCE REPORT: OVER .19 0
Run three tests using a stand and must have a spread of .00 used. X 0.10% STANDARD - MUST READ 0.08% STANDARD - MUST READ 0.04% STANDARD - MUST READ TEST 1 0.098 g/210L INDICATE THE NUMBER OF BREATH TO SATISFACTORILY AND WITHIN ESTABLISHED LEST SATISFACTORILY AND WITHIN ESTABLISHED LEST SIGNATURE SIGNATURE EXPIRE EXPIRE TYPE II PERMIT NUMBER EXPIRE EXPIRE EXPIRE TYPE II PERMIT NUMBER EXPIRE EXPIR	dard solution. All of or less. Mark BETWEEN 0.095% AN BETWEEN 0.076% AN BETWEEN 0.038% AN TEST 2 0.098 TEST 2 0.098 TESTS IN THE FOLLOW OF THE SIDE IN THE SIDE	three tests muthe box correspond of the box	st be within ±5% onding to the state of the	andard solution being 3 g/210L CENANCE REPORT: OVER .19 0 TO OPERATE



Airgas USA LLC (LAB) 3500 Bernard Street St, Louis, Mo. 63103 Ph: (314) 533-3100 Fax: (314) 533-7328

Certificate of Analysis

Customer Name Exclusive Supplier Intoximeters, Inc. 2081 Craig Road St. Louis, Mo 63146

Test Date: 13-Mar-2023

Lot # AG306807 Model 108

Exp Date 9-Mar-2025

Cyl. Type 108 Component Ethanol

Nitrogen

Certified Concentration 0.100 ± 2% BrAC (272 ppm)

Certification Traceable to N.I.S.T. RGM and to CRM Ethanol Standards:

RGM Serial No.	Concentration
EB0010581	391.8 ppm
EB0010570	259.8 ppm
EB0010285	209.0 ppm
EB0010561	103.7 ppm
EB0010681	52.22 ppm

RGM Serial No.	Concentration
EB0010603	392.5 ppm
EB0010559	258.9 ppm
EB0010562	104.2 ppm
EB0010579	52.94 ppm
	- 1

CRM Serial	No
CC727481	
CC727496	

Concentration 800.0 ppm 253.0 ppm CRM Serial No. CC727493 CC727498

Concentration 390.0 ppm 150.0 ppm

Analytical Method: NDIR

Digitally signed by Quality Control Reason:Dry gas standard certification of analysis Location:Airgas USA LLC (Lab) Date:03.16.2023 13:02

Approved for Release:

Rod Marsala

ISO 17025:2017 A2LA accredited. Certificate Number 3082.06 ISO 17034:2016 A2LA accredited. Certificate Number 3082.07



STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM



PERMIT TYPE II

BRETT HAZELRIGG


is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

ALCO-SENSOR IV WITH PRINTER, INTOX EC/IR II

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

DATE 4/2/2024	Mike Masson
NUMBER 240078	DIRECTOR OF STATE PUBLIC HEALTH LABORATORY
WONDELL ENGINEERING	Daven J. Nichelson
EXPIRES 4/2/2026	
MO 580-0771 (G-10)	DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES

LAB-4 (R6-10)



The named cardholder is authorized to operate an evidential breath alcohol instrument for the determination of the alcoholic content in breath form of expired ail in Missouri.

Operator HAZELRIGG, BRETT

Permit No 240078

Date Issued 4/2/2024 Date Expires 4/2/2026

