

### MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

#### INTOX DMT MAINTENANCE REPORT

REPORT #1

THIOX DIVITION THE CONTRACTOR	TEL OIL				
Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.					
NAME OF AGENCY 500016 Higginsville Police Department			DATE OF INSPECTION 12/02/2024		
LOCATION OF INSTRUMENT (STREET AND CITY)  12 W 19th Street, Higginsville, MO			TIME OF INSPECTION 09:38:03		
CHECKLIST: Place a mark in the box by each item if found to be satisfactory or is operating within established limits. (Write in observed values where determined). Unmarked items must be corrected before using instrument.					
☑ DIAGNOSTIC RECORD					
DATE AND TIME 12/02/2024 09:38:06					
☑ PROGRAM ☑ FILTER 1					
☑ SAMPLE CHAMBER 48.8°C					
☐ BREATH TUBE 48.1°C ☐ ☐ FILTER 3					
☑ PUMP ☑ INTERNAL STANDARD					
BREATH ANALYZER ACCURACY STANDARDS					
☐ SIMULATOR STANDARD ☐ COMPRESSED ETHANOL-GAS MIXTURE					
☑ STANDARD SUPPLIER INTOXIMETERS	LOT#_AG3065	503 E	XP. DATE <u>03/06</u>	8/2025	
SIMULATOR TEMP (34°C ± 0.2°C)	SIM. SN	SIM. NIS	T EXP DATE		
<ul> <li>CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) Run three tests using a standard. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard being used.</li> <li>☑ 0.10% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE</li> <li>☐ 0.08% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE</li> <li>☐ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE</li> </ul>					
TEST 1: 0.098	EST 2: <b>0.098</b>	TEST	TEST 3: 0.098		
☑ PERFORM R.F.I. TEST					
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:					
REFUSALS: 0 004: 25 .09	509: 0 .1014:	1 .151	9: <b>0</b>	OVER .19: 1	
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY)					
INSPECTING OFFICER SIGNATURE PRINT FULL NAME					
TYPE II PERMIT NUMBER		TON L DINOVI			
230215	10/06/2025	660-584-2104			
RETURN COMPLETED REPORT TO THE  Breath Alcohol Program, Missouri Department of Health and Senior Services by mail, fax, or email					



## STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM



# PERMIT TYPE II

## **QUINTON L. DINOVI**

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

### **INTOX DMT**

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections

DATE10/6/2023	Mike Massur		
	DIRECTOR OF STATE PUBLIC HEALTH LABORATORY		
NUMBER 230215			

NUMBER 230215

EXPIRES 10/6/2025

577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

MO 580-0771 (6-10)

The Hotel

DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES

Daves J. nichelson

LAB-4 (R6-10

