

### MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

#### INTOX DMT MAINTENANCE REPORT

REPORT #1

| The state of the s      |                            |                           |                                  |             |
|---|----------------------------|---------------------------|----------------------------------|-------------|
| Complete this report at the time of the regular mont<br>Complete this report whenever the instrument is se<br>Retain the original and send a copy within 15 days  | rviced or repaired and v   | vhenever it is place      |                                  |             |
| INTOX DMT SN. NAME OF AGENCY Missouri State   | Highway Patrol             | *                         | DATE OF INSPECTION 03/01/2025    |             |
| LOCATION OF INSTRUMENT (STREET AND CITY)  Branson West PD,110 Silver Lady Ln,Branson West,MO  |                            |                           | TIME OF INSPECTION 14:43:46      |             |
| CHECKLIST: Place a mark in the box by each item if found to be satisfactory or is operating within established limits. (Write in observed values where determined). Unmarked items must be corrected before using instrument.   |                            |                           |                                  |             |
| ☑ DIAGNOSTIC RECORD   |                            |                           |                                  |             |
| DATE AND TIME <u>03/01/2025 14:43:48</u> ☑ DETECTOR   |                            |                           |                                  |             |
| ☑ PROGRAM ☑ FILTER 1  |                            |                           |                                  |             |
| SAMPLE CHAMBER 48.8°C   |                            |                           |                                  |             |
|   |                            |                           |                                  |             |
| ☑ PUMP  |                            | INTERNAL STA              | NDARD                            |             |
| BREATH ANALYZER ACCURACY STANDARDS  |                            |                           |                                  |             |
| ☐ SIMULATOR STANDARD ☐ COMPRESSED ETHANOL-GAS MIXTURE   |                            |                           |                                  |             |
| ☑ STANDARD SUPPLIER INTOXIMETERS  | LOT#_ <i>F</i>             | AG335303                  | EXP. DATE 12/1                   | 19/2025     |
| ☐ SIMULATOR TEMP (34°C ± 0.2°C)   | SIM. SN                    |                           | SIM. NIST EXP DATE               |             |
| <ul> <li>         □ CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)         Run three tests using a standard. All three tests must be within ±5% of the standard value and must have a spread         of .005 or less. Mark the box corresponding to the standard being used.         □ 0.10% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE         □ 0.08% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.044% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.044% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.044% INCLUSIVE         □ 0.04% STANDARD - MUST READ BETWEEN 0.044% INCLUSIVE         □ 0.04% STANDARD - MUST RE</li></ul> |                            |                           |                                  |             |
| TEST 1: 0.099   | EST 2: 0.099               |                           | TEST 3: 0.099                    |             |
| ☑ PERFORM R.F.I. TEST   |                            |                           |                                  |             |
| INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:  |                            |                           |                                  |             |
| REFUSALS: 0 004: 6 .0   | 0509: 0                    | .1014: 1                  | .1519: 0                         | OVER .19: 0 |
| LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFIESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY)  | CATION THAT WAS MADE TO RE | ESTORE THE INSTRUMEN      | IT TO OPERATE SATISFACTORILY AND | WITHIN      |
| Changed time  |                            |                           |                                  |             |
| INSPECTING OFFICER  |                            |                           |                                  |             |
| SIGNATURE - Mr.   |                            | PRINT FULL NAME  B A HALL |                                  |             |
| TYPE II PERMIT NUMBER 240243  | EXPIRATION DATE 11/27/2026 | TELEPHONE                 | NUMBER<br>05-6868                |             |
| RETURN COMPLETED REPORT TO THE  Breath Alcohol Program, Missouri Department of Health and Senior Services by mail, fax, or email  |                            |                           |                                  |             |



## STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM



# PERMIT TYPE II

## **BRANDON A. HALL**

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

# **ALCO-SENSOR IV WITH PRINTER, INTOX DMT**

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

11/

| DATE    | DATE11/27/2024    | adam / fuli  |  |  |
|---------|-------------------|--|--|--|
| V 10    |                   | DIRECTOR OF STATE PUBLIC HEALTH LABORATORY           |  |  |
| NUMBER  | 240243            |  |  |  |
| EXPIRES | XPIRES 11/27/2026 | Davla I. Nichelson                                   |  |  |
|         |                   | DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES |  |  |

MO 580-0771 (6-10)

LAB-4 (R6-10)



The named cardholder is authorized to operate an evidential breath alcohol instrument for the determination of the alcoholic content in breath form of expired air in Missouri.

Operator HALL, BRANDON Permit No 240243

