



MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES
 STATE PUBLIC HEALTH LABORATORY
 BREATH ALCOHOL PROGRAM
DATAMASTER MAINTENANCE REPORT

REPORT #6

RECEIVED
 By Carol Day at 3:14 pm, Aug 11, 2015

Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 3 months).
 Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service.
 Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.

DATAMASTER SN 940097	NAME OF AGENCY Sweet Springs P.D.	DATE OF INSPECTION 08/01/2015
LOCATION OF INSTRUMENT (STREET AND CITY) 324 S. Miller Sweet Springs		TIME OF INSPECTION 09:52

CHECKLIST: Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unmarked items must be corrected before using instrument.

<input checked="" type="checkbox"/> DIAGNOSTIC CHECK (PRINTOUT ATTACHED)	DATE AND TIME (from printout) 08/01/15 09:52
<input checked="" type="checkbox"/> COMPUTER	<input checked="" type="checkbox"/> DETECTOR
<input checked="" type="checkbox"/> PROGRAM	<input checked="" type="checkbox"/> FILTERS
<input checked="" type="checkbox"/> HEATERS SAMPLE CHAMBER 49° °C	<input checked="" type="checkbox"/> QUARTZ STANDARD
<input checked="" type="checkbox"/> FLOW DETECTOR	<input type="checkbox"/> CALIBRATION
<input checked="" type="checkbox"/> PUMP HIGH SPEED	<input checked="" type="checkbox"/> PRINTER

INDICATOR LIGHTS

SIMULATOR SOLUTION SUPPLIER **RepCo marketing** LOT # **15001** EXP. DATE **5/20/12**

SIMULATOR TEMP (34°C ± 0.2°C) **34°** °C SIMULATOR SN **SD3 144** EXP. DATE **8/25/15**

CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)

Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)

0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE
 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE
 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE

TEST 1 101%	TEST 2 100%	TEST 3 100%
--------------------	--------------------	--------------------

PERFORM R.F.I. TEST (PRINTOUT ATTACHED) **RFI detected.**

INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)

REFUSALS 0	(0-.04) 0	(.05-.09) 0	(.10-.14) 0	(.15-.19) 0	OVER .19 0
-------------------	------------------	--------------------	--------------------	--------------------	-------------------

LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY).
This instrument is operating within dept of Health Specification using 100% solution from RepCo marketing lot # 15001 exp date 5/20/12 No adjustments have been made

INSPECTING OFFICER

SIGNATURE Melvin Taber	PRINT FULL NAME Melvin Taber
TYPE II PERMIT NUMBER/EXPIRATION DATE 230211 10/02/15	TELEPHONE NUMBER 660.335.6823

RETURN COMPLETED REPORT TO THE:
 Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office
 2875 James Blvd.
 Poplar Bluff, MO 63901

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc.

LOT NUMBER: 15001

EXPIRATION DATE: May 20, 2017 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 15001 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain .1206 gms/dl +/- .003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of .100 +/- 3% gms/210L Breath when heated to 34 Degrees Celsius +/- 0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is May 21, 2015
The expiration date for this lot number is May 20, 2017 at
11:59 p.m.

This document is a true representation of the original Certificate of Analysis.



Cecil B. Garner, President
RepCo Marketing, Inc.

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI
SWEET SPRINGS POLICE DEPARTMENT

BAC DATA MASTER SERIAL NUMBER 040807
00/01/15

TESTING OFFICER:
TAGER/MELVIN/L
OFFICER I.D.# 902
PERMIT NUMBER: 298211
EXPIRATION DATE: 10/00/15
MISCELLANEOUS DATA:
MONTHLY MAINTENANCE TEST
SUPERVISOR MODE

--- SUPERVISOR MODE ---

BLANK TEST	.000	09:52
INTERNAL STANDARD	VERIFIED	09:52
EXTERNAL STANDARD	.101	09:52
BLANK TEST	.000	09:59
EXTERNAL STANDARD	.100	09:59
BLANK TEST	.000	10:00
EXTERNAL STANDARD	.100	10:00
BLANK TEST	.000	10:01

H = 0
STB. : .000
AVG. : .1000

Operator Signature

2208-02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI
SWEET SPRINGS POLICE DEPARTMENT

BAC DATA MASTER SERIAL NUMBER 040807
00/01/15
09152

--- DIAGNOSTIC CHECK ---

COMPUTER:	OKAY
PROGRAM (04-07-2009):	OKAY
HEATERS	
SAMPLE CHAMBER:	40:
FLOW DETECTOR:	OKAY
PUMP	
HIGH SPEED:	OKAY
DETECTOR:	OKAY
FILTERS:	OKAY
URATE STANDARD:	OKAY
CALIBRATION:	OKAY

PRINTER TEST

1"0420"0411-1-8123456789:11-17-ABOUEE
HIJKLNOPQRSTUVWXYZ1234567890
abcdefghijklmnopqrstuvwxyz(1)14

Operator Signature

2208-02

Face This Side Down - This Edge In First

**BAC DataMaster
Evidence Ticket**

STATE OF MISSOURI
SWEET SPRINGS POLICE DEPARTMENT

BAC DATA MASTER SERIAL NUMBER 948097
09/01/15

ARREST TIME: 0948

SUBJECT NAME:

TABER/MELVIN/L

DOB: 01/23/53 SEX: M

STATE I.D.L.: MO/123456789

ARRESTING OFFICER:

TABER/MELVIN/L

OFFICER I.D.L.: 990

TESTING OFFICER:

TABER/MELVIN/L

OFFICER I.D.L.: 992

PERMIT NUMBER: 290211

EXPIRATION DATE: 10/02/15

MYCELLANEOUS DATA:

MONTHLY MAINTENANCE TEST

RADIO INTERFERENCE TEST

BREATH ANALYSIS ---

BLANK TEST	.000	10:05
INTERNAL STANDARDS	VERIFIED	10:00
RADIO INTERFERENCE		

Operator Signature _____