


 MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES  
 STATE PUBLIC HEALTH LABORATORY

**ALCO-SENSOR IV WITH PRINTER MAINTENANCE REPORT**

REPORT #7

Complete this report in duplicate at the time of the regular monthly preventative maintenance check, and whenever instrument is repaired. Send copy to Department of Health and Senior Services; retain original in department file.

ALCO SENSOR IV SN 097408	PRINTER SN 096.3580.872	DATE OF INSPECTION 03/03/2020
LOCATION OF INSTRUMENT (STREET AND CITY) 103 State Highway H, Miner, MO 63801		TIME OF INSPECTION 9:38 am

**CHECKLIST:** Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unmarked items must be corrected before using instrument.

 DIGITAL READOUT (ALL ELEMENTS OPERATIONAL)

 TEMPERATURE OF ALCO SENSOR (10°C - 40°C)

 PRINTER WORKING PROPERLY

 TIME AND DATE DISPLAYING PROPERLY

**BREATH ALCOHOL ACCURACY STANDARDS**
 SIMULATOR SOLUTION  COMPRESSED ETHANOL-GAS MIXTURE

 STANDARD SUPPLIER RepCo Marketing Co. LOT # 19001 EXP. DATE 03/12/2021
 SIMULATOR TEMPERATURE (34°C ± 0.2°C) 33.98 SIMULATOR SN MP4948 SIMULATOR EXP DATE 03/03/2020
 CALIBRATION CHECK – (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)

Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)

- 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE  
 0.080% STANDARD - MUST READ BETWEEN 0.076% and 0.084% INCLUSIVE  
 0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE

TEST 1 ➡ .096

TEST 2 ➡ .098

TEST 3 ➡ .097

 RFI DETECTOR OPERATING

INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:  
(DO NOT INCLUDE SELF-ADMINISTERED TESTS)

REFUSALS	0	(0-.04)	0	(.05-.09)	0	(.10-.14)	0	(.15-.19)	0	(OVER .19)	0
----------	---	---------	---	-----------	---	-----------	---	-----------	---	------------	---

List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary).

**INSPECTING OFFICER**

SIGNATURE 	PRINT NAME Jessica L. Martin
TYPE II PERMIT NUMBER/EXPIRATION DATE 290231 10/01/2021	TELEPHONE NUMBER (573) 471-8568

Return completed report to the: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office  
2875 James Boulevard  
Poplar Bluff, MO 63901

AS IU Serial no: 897488  
Version no: 532B

TEST RECORD 88571

Temp Date Time 210L

Air Blank:  
03/03/20 09:31 .888  
Calibration Check:  
24 03/03/20 09:31 .896

Subject Name

Test #1

Subject I.D.

Operator Name, I.D.

Martin 290231

Location

103 St. Hwy H

Miner, MO 63801

AS IU Serial no: 897488  
Version no: 532B

TEST RECORD 88572

Temp Date Time 210L

Air Blank:  
03/03/20 09:34 .888  
Calibration Check:  
25 03/03/20 09:34 .888

Subject Name

Test #2

Subject I.D.

Operator Name, I.D.

Martin 290231

Location

103 St. Hwy H

Miner, MO 63801

AS IU Serial no: 897488  
Version no: 532B

TEST RECORD 88573

Temp Date Time 210L

Air Blank:  
03/03/20 09:36 .888  
Calibration Check:  
26 03/03/20 09:36 .897

Subject Name

Test #3

Subject I.D.

Operator Name, I.D.

Martin 290231

Location

103 St. Hwy H

Miner, MO 63801

AS IU Serial no: 897488  
Version no: 532B

TEST RECORD 88574

Temp Date Time 210L

Air Blank:  
12 03/03/20 09:38

Subject Name

Test RET

Subject I.D.

Operator Name, I.D.

Martin 290231

Location

103 St. Hwy H

Miner, MO 63801