

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

INTOX DMT MAINTENANCE REPORT

REPORT #1

WARE THE TOX DIVIT WING THE TAY THOU	L IKLI OKT				
Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.					
NAME OF AGENCY 500194 Canton Police Department			DATE OF INSPECTION 05/07/2024		
LOCATION OF INSTRUMENT (STREET AND CITY) 108 N 5th St, Canton, MO			TIME OF INSPECTION 14:43:11		
CHECKLIST: Place a mark in the box by each item if found to be satisfactory or is operating within established limits. (Write in observed values where determined). Unmarked items must be corrected before using instrument.					
☑ DIAGNOSTIC RECORD					
DATE AND TIME <u>05/07/2024 14:43:13</u> ☑ DETECTOR					
☑ PROGRAM ☑ FILTER 1					
☑ SAMPLE CHAMBER 48.8°C	SAMPLE CHAMBER 48.8°C				
☑ BREATH TUBE 48.1°C ☑ FILTER 3					
☑ PUMP ☑ INTERNAL STANDARD					
BREATH ANALYZER ACCURACY STANDARDS					
☐ SIMULATOR STANDARD	LATOR STANDARD COMPRESSED ET			HANOL-GAS MIXTURE	
	LOT#_	AG220102	EXP. DATE <u>07/20</u>	0/2024	
☐ SIMULATOR TEMP (34°C ± 0.2°C)	SIM. SN		SIM. NIST EXP DATE		
 □ CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) Run three tests using a standard. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard being used. □ 0.10% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE □ 0.08% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE □ 0.04% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE 					
TEST 1: 0.098 TEST 2: 0.097			TEST 3: 0.097		
☑ PERFORM R.F.I. TEST					
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT:					
REFUSALS: 0 004: 0	0509: 0	.1014: 0	.1519: 0	OVER .19: 0	
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFI ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY)	ICATION THAT WAS MADE TO R	RESTORE THE INSTRUMENT TO	OPERATE SATISFACTORILY AND W	I	
MEETS DHSS STANDARDS.					
INSPECTING OFFICER					
SIGNATURE	PRINT FULL NAME ZACHARY S				
TYPE II PERMIT NUMBER 774 CV 240034	02/05/2026	TELEPHONE NUM 660-385-2			
RETURN COMPLETED REPORT TO THE Breath Alcohol Program, Missouri Department of Health and Senior Services by mail, fax, or email					